

PART CHANGE OVER GUIDELINE & CHECK SHEET FOR PACKING TABLE

Date	Entry No.	Part No.	Operator	Supervisor	Plating Thickness (0.12 mm)	Availability of these parts in Pak. material bin	Take the sticker from supervisor for the part as per colour code.	Handover completed part to supervisor	Handover material part to operator	Put the part in respective bin	Inspected part to be kept in yellow bin.	Remove material from the top in respective bin.	Check the table to avoid clash with other bin.	Feed material in the table from packing area.	Handover the part to operator	Remark	Signature
24.12.2024	07	0272	Eqaraj Nangan	Nangan	8.5	X	✓	X	✓	✓	✓	✓	✓	✓	✓	OK	
24.12.2024	11	8679	Suresh	11	9.8	X	✓	X	✓	✓	✓	✓	✓	✓	✓	OK	
24.12.2024	08	0072	Nande	11	10.7	X	✓	X	✓	✓	✓	✓	✓	✓	✓	OK	
24.12.2024	05	3261	Laxman	11	11.7	X	✓	X	✓	✓	✓	✓	✓	✓	✓	OK	
24.12.2024	614	8549	Shel	Nangan	10.5	X	✓	X	✓	✓	✓	✓	✓	✓	✓	OK	
24.12.2024	09	3910	Dona	11	11.7	X	✓	X	✓	✓	✓	✓	✓	✓	✓	OK	
24.12.2024	10	3949	Diksha	11	9.8	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	OK	
24.12.2024	16	8531	Digambar	11	10.7	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	OK	
24.12.2024	616	3587	Ruhm	11	11.7	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	OK	
24.12.2024	618	0025	Sanjita	Nangan	9.7	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	OK	
24.12.2024	03	0272	Sonali	11	10.2	X	✓	X	✓	✓	✓	✓	✓	✓	✓	OK	
24.12.2024	04	0410	Govind	11	11.7	X	✓	X	✓	✓	✓	✓	✓	✓	✓	OK	
24.12.2024	04	8184	Govind	11	10.8	X	✓	X	✓	✓	✓	✓	✓	✓	✓	OK	
24.12.2024	06	8361	Kaie	11	11.4	X	✓	X	✓	✓	✓	✓	✓	✓	✓	OK	
24.12.2024	07	0105	Sonali	11	7.9	X	✓	X	✓	✓	✓	✓	✓	✓	✓	OK	
24.12.2024	08	8353	Nande	11	8.4	X	✓	X	✓	✓	✓	✓	✓	✓	✓	OK	
24.12.2024	614	8071	Shel	Nangan	9.7	X	✓	X	✓	✓	✓	✓	✓	✓	✓	OK	
24.12.2024	09	3941	Dona	11	9.8	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	OK	
24.12.2024	16	3835	Digambar	11	11.7	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	OK	
24.12.2024	03	3856	Sonali	11	10.7	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	OK	

[Handwritten Signature]