








ONE POINT LESSON



murugappa

Theme		K70 Damper - Visual Defects		OPL No.	FBD / OPL / 330E
Purpose		Visual - Awareness given to Final inspection		Date	03.05.2022
Category		Basic Knowledge	Kaizen Cases	Final Inspection	
		✓		Circle Leader	Prepared By
			Trouble Cases	S.Janarthanam	K.Senthil Kumar
			✓		
		RIGHT (✓)		WRONG (x)	
					
		No visual defects		K70 damper clutch black/ red batch mark part NG	
Teacher	K. Senthil				
Sign					
Student	Y. Alada S. J.S				
Sign				Praba	
		a. krishnan			