



Expect the Best.

DEKSON CASTINGS LTD

QUALITY ALERT

Problem : Hairline Crack Mark

Part Name : Outer Tube 9080



Occurance date: 17.12.2022

Issue date: 17.12.2022

Exit date:

Process: GDC

Number of defect: 01 Nos.

Reject This type of Hairline Crack Part during Process and Final Inspection

वरील चित्रात दाखवल्या प्रमाणे लग वर जर क्रॅक लाईन दिसत असेल तो पार्ट रिजेक्ट करावा

PREPARED BY : Shrinivas

APPROVED BY : Ashok Doifode