

# Supplier Defect Communication Sheet

E-93, MIDC Waluj, Aurangabad, 431136.

Sr.No	Date	Part Number	Part Name	Supplier Name
2	08-04-2023	F2PH02212B	COVER CAP (Ø33 SPD)	M/S. SHARP ENGINEERS.

**Defect Details:- 3 mm height found under size by 1.5 mm.**

## Defective Part Photograph



Issue Reported On	08-04-2023
Location	Seat Pipe Line
Rej Qty	11
Lot Qty	1,000
Invoice Number	232400592
Invoice Date	07-04-2023
Remarks	All rejected part send back to you