

**Implemented CA / Improvement**

**Concern :**

Gauge bush ID 23.51 mm

**Check Point**


07

**Regularized on:**

19.07.23

**BEFORE**

**AFTER**



**Gauge bush ID 23.51 mm**

**Gauge bush ID 23.4 mm manufacturing under Process**