Δ	f	t	e	r
$\overline{}$	ч		_	

<i>[</i>	7	BG	FASTENING & ENGG IND	LTD					
	SAMPLE INSPECTION REPORT								
CUST	OMER NAME : EN	IDURANCE PVT LTD	CUSTOMER PART NO: F2LY003120	BGF NO	: 391	3	DATE OF INSPECTIO N		
CUST	OMER STANDARD :		DESCRIPTION: M8X1.25X27 SHC BOLT	BGF DRG.REV.N	0:				
CUST	.STD.REV.NO :	С	CUSTOMER DRG NO: F2LY003120	SAMPLE QTY	: 05 N	22.9.2023			
21	SST	168 HRS for white rust,480 HRS For read rust	Under observation			Salt Spary	U/O		
22	Surface Apperance	No Burr, No Sharp Edges	No Burr,No Sharp Edges			Visual	ок		
23	Thread Damages	Protect thread From Damages	No any Thread Damage			TRG / Visual	ок		
Note:- Sampling size 5 nos each bin for parameters-length, threading length & head height.									
Supplier Remarks				Remarks					
Prepared By :				Approved By :	i				

Sampling added 5 nos for each bin of material.