



HPPL- QUALITY ALERT



Doc No. :- F/QA/37
Rev. No/ Date :- 00/01.06.2019
Page No. :- 01 of 01

PART NUMBER :	520JT05102	DATE	20.02.2024
PART NAME :	PLTE CLUTCH	QUANTITY REJECTED	3900
CUSTOMER :	ETL	TOTAL DISPATCH QUANTITY	17400
PROBLEM DESCRIPTION	CRACK OBSERVED		



OK

Part checked in visual and check mark(white dot) to be applied.



NOT OK

Part checked in visual and check. Crack parts to be put into rejection bin.

PREPARED BY - NS

APPROVED BY - KW