




























CAST 4 ALUMINIUM PVT LTD

Visual Sample Display

Part Name		JA Housing clutch / k70 Housing		
Part No		3620053413		
Customer Name: Endurance Technologies Pvt.Ltd (Transmission Div)				
Sr.No	Defect Discription	Inspection Method	Not OK Sample	OK Sample
1	Could Shut			
2	Blow Hole			
3	Crack			
4	Catching			
5	Gate Area Blow hole			
6	Non filling			
8	Hole Shift			
9	Pin Dip & Projection \pm 0.3 mm			
10	Auto Punching			

Prepared By: Qaseemuddin Syed

Approved By: **AppaSaheb Jadhav**

