

'Q' - GATE

**QUALITY ALERT**  
Customer: Gabriel India Ltd, Hosur Date: 22.11.18  
Name: White bolt Location: Final inspection

M10 thread  
operation  
missing



ING  
995

